















## Bestendigheidlijst t.b.v. afdichtingen

	NBR	EPDM	FPM	CR	SBR	ACM	AU	IIR	NR	PPPM	CSM	FMVQ	MVQ	PS	PTFE
Zwaveligzuur	2	2	1	2	2	4	4	2	2	1	1	-	4	4	-
Zwavel trioxide droog	4	2	2	4	3	4	-	2	3	1	4	2	2	4	1
Zwavel vloeistoffen	2	2	1	2	2	4	-	2	2	-	2	2	4	4	1
Zwavelzuur 10% (60°C)	2	1	2	2	2	-	4	1	2	1	1	-	2	-	1
Zwavelzuur 25% (60°C)	2	1	2	2	2	-	4	1	2	1	1	-	2	-	1
Zwavelzuur 50% (60°C)	4	1	2	2	4	-	4	1	4	1	1	-	4	-	1
Zwavelzuur 75% (60°C)	4	2	2	4	4	-	4	4	4	1	2	-	4	-	1
Zwavelzuur 96% (60°C)	4	4	2	4	4	4	4	4	4	1	4	4	4	4	1
Zwavelzuur rokend	4	4	1	4	4	-	4	4	4	1	4	-	4	-	1

